

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

### -- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.

The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

### -- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.

# TOROUE TUBE THE INTERNATIONAL NEWS PUBLICATION FOR MEMBERS OF THE 1937-1938 BUICK CLUB. 1937 1938

VOLUME XVII - NUMBER 4 - MARCH/APRIL 1999



### BY HARRY LOGAN (#651) EDITOR

### CONGRATULATIONS!

Our membership has now reached 593 members. We should break 600 members before our September renewal. This is the highest membership in the Club's 19 year history!

It looks as if our Club has brought together a membership of '37 & '38 Buick lovers who appreciate a well rounded publication for ve-

hicles that have earned their rightful place in history. Not only is it a credit to these vehicles but a credit to a group of world wide friends who find the camaraderie of this Club a refuge in the world of mass communication. Thanks to

all for your continued support.

Ed Doucette (#220) in Alabama writes: "I have an export model 1938 Special with right hand drive. The firewall data plate reads Model 41X. The frame has the word "export" stamped on it. The frame data plate begins with a '1', indicating Flint as the assembly plant. It is a Fisher

bodied sedan. According to production figures there were 2,681 Model 41X's exported."

"I would like to find out how many of the export models with Fisher bodies still exist. If you have one, please let the Editor know so he can tabulate the num-

bers and let the members know the results. Thank you."

This 1937 Century Sedan Model 61 belongs to Anthony Wright (#1192) in New York City.

The bottom photo shows Mike Esposito of Glusco, NY, located right on the Hudson River. Mike rebuilt the engine and rebuilt and detailed everything under the hood. Mike is a perfec-

tionist, he does not cut corners! In the background is 1939 Buick Special Sport Coupe. Mike just finished. Unfortunately, it was rear ended and is now a total loss! What a shame!

The next photograph, on page 2.

is from Sam Mahle (#1187) in Clarion, PA. He recently finished restoring the 1937 Century Coupe he drove while in college nearly 40 years ago. It's painted Sudan Blue and Sam says he gets a lot of compliments on the car. Sam tested his speedometer by having a friend in a modern car flash her headlights when she hit 60 mph.

> Sam says his '37 speedometer indicated 62 mph which he feels is accurate enough.

This next photo on page 2 shows a 1938 Special that has a unique Sedan Delivery body by Norwegian coachbuilder lacobsen in Oslo. The car is now







IN 1980 BY DAVE LE






in Sweden. Jacobsen also made funeral cars, ambulances and police cars on a Buick chassis

in the 1930's. Thanks to Norway member Lars Guilliksrkud (#1013) for sharing this interesting vehicle photo.

This ad, at the top of page 3, showing a 1938 Special sedan was used to advertise the 1969 Buick Electra. It reads: "A lot has happened since you were a kid. A lot

has changed. But not Buick. Sure it's b i g g e r a n d smoother and faster and quieter and richer and more luxurious. But it's still a Buick. And there's still no confusing Buick with any



### =TORQUE TUBE=

### You can now find your '37-'38 Buick Club on the World Wide Web:

http://www.classicar.com/clubs/buick/buick.htm

The **TORQUE TUBE** is published every two months for the enjoyment of the **1937-1938 Buick Club**. Membership dues are \$34.00 per year US, \$35.00 per year Canada or Mexico and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the **1937-1938 Buick Club**.

Please send all articles, ads subscriptions and inquires, etc. to:

The TORQUE TUBE 1005 RILMA LANE LOS ALTOS, CA 94022 USA

You can reach Harry Logan by PHONE/FAX (650) 941-4587 or by E-mail: harrylogan@earthlink.net

Printer Liaison: Bill Olson, #427
Printer: Conrads Printing, Lancaster, Ohio

All rights reserved. No part of this newsletter may be reproduced in any form without written permission from THE TORQUE TUBE

other car." Thanks to Walt Morrison (#833) in Canada for sharing this ad.

New member Brian Jensen (#1372) in Baltimore, MD recently purchased a 1938 Special 2-Door Sedan Model 48. He writes: "After trying to readjust the front seat which barely moved, I took off the trim pieces to see what the problem was underneath.

A huge accumulation of dust and dirt appeared to be the culprit, so I got out the vacuum and attacked it with a crevice tool. Other than a scrap of paper towel or candy wrapper, the vacuum lodged on three items it


couldn't suck up. The three items obviously had not moved since they were tossed under the seat when the car was new!

The first being the little folder of instructions for the accessory clock

with its string for hanging on the setting knob. Then came a horse racing stub from July, 1938 (did they drive first thing to the races to show off their new car?). The last item appears to be the first oil change reminder..... 'Change motor

When you were a kid you dreamed of the day you could own a Buick







oil....2,531 miles.' There must have been already 31 miles on the odometer when purchased.

I thought it was rather amazing these things sat there, undisturbed, for 60 years! I carefully probed further to find something else; jewelry, money, etc., but nothing turned up....drat!"

This black 1938 Century Phaeton Model 60C is a very rare car. (middle photo) Buick only produced 208 plus another 11 for export. This car belongs to new member **David Schofield** (#1397) of Pales Verdes, CA.

It is in average condition.

It looks good. The seats are vinyl, not leather. The engine is original, but has had the head replaced and new rings and bearings installed several

times during it's life. The car has been driven 285,000 miles over the past 60 plus years. It has never been restored!

The bottom two photos show another 38-60C. It's Raphael (light) green and lives in Or-





egon. It's in nice condition with green leather upholstery.

This photo of a '38 Buick Special sedan, at the top of the page, was emailed to me by new member

Mark Garcia (#1390) in Fremont, California.

The next photo that was sent by Mark is this 1941 photo by famous photographer Andreas Feininger entitled "CARS." How many cars can you identify?

This cartoon, at the top of page 5, appeared in the March, 1942 issue of Motor Age magazine.

The first photograph at the top of page 5 shows a '38 Special Business Coupe Model 46 with a semi-automatic transmission. It belongs to Fred Graybeal (#1124) in Ft. Worth. TX. The car was formerly part of the Harrah's Car Collection in Reno, NV. Fred also has a 1938 Special Phaeton Model 40C with a semi-automatic transmission.

Club member Peter Breitenstein (#989) in Namibia, Africa writes: "Regarding the excellent article on overheating (Cavitation Cure) in the Nov/Dec issue. Some interesting ideas have come to light through the Ford Sidevalve people, (my Brother-in-Law has a '46 which he loves and cherishes). They have found out that the water flow through the radiator is too fast at high speeds, it therefore does not have enough time to cool down on its way through the radiator. First they tried to solve the problem by fitting a restriction into the upper radiator hoses, which seemed worked to some extent. Now someone has come along and modified the water pumps by removing ev-



Fords. Whether the fix can be used on our Buicks, as they only have one pump as opposed to the two on the Fords, would be interesting to find out. Perhaps someone is willing to give it a try? I

would, but have no spare pump to experiment on."

ery second fin, or

vane, from the im-

peller, thereby

ending up with

three fins instead

This they say

solves all high-

speed overheating

fins.

six

New member E. H. Trezevant, Jr. (#1404) sent this next photo of his 1937 sidemounted Buick hearse. He operates Trezevant Funeral Home in Columbia, South Carolina and reports the hearse is in use and is the favorite choice of his clients.

The last photo, on page 5, shows a 1938 Roadmaster 4-door Touring Sedan, Model 81. It was the most popular car in the Roadmaster series. Buick built 4,505 for

domestic sales and 199 for export. It cost \$1,645 and weighed 4,245 pounds (1,930 kg). This fine restoration, wearing dual sidemounts and dual fog lights is owned by John Roche of Baltimore, MD. Thanks to **Joe Giordano** (#333) for sharing this.

In our last *Torque Tube* (Jan/Feb) we featured an article on *Bill Whyte's* (#968) 1938 Century Convertible Coupe in Scotland. To keep the record straight, Bill has pointed out a couple of errors in the article.

The article states that 14 38-66Cx's went to the UK. It should have read 14 RHD 38-66Cx's were produced for export. Some went to the UK



and other possible destinations (RHD countries) were Australia, New Zealand, South Africa and Sweden. Sweden has since switched to LHD.

Bill goes on to point out that the British Buick agent, Lendrum & Hartmann, chrome plated the valve and sparkplug covers, not the valve and pushrod covers. Thanks for the corrections Bill.

'37-'38 Buick Club member Cecil Don (#637) in California is running for the Buick Club of America (BCA) National Board of Directors. This issue features his '38 Century Sedan on our front

and back covers. BCA members will receive a ballot with the next issue of The Bugle (April, 1999 issue). I know Cecil to be a congenial and dedicated Buick booster. He helped produce the 1991 Sacramento National Meet and has served as Director of the Capitol Chapter of the BCA in Sacramento, CA.

Non-member Scott Gillis in California sent me an e-mail requesting a ride in a '38 Buick for his parents. In late May, he and his wife and four children will be flying back to Baltimore, MD to help celebrate his parent's 50th anniversary. His father bought a '38



"I'm atraid I got disgusted with your

Buick sedan in the early '60's. It was his pride and joy. He owned and loved driving it until around 1985. (Maybe one of our members now owns it). Would anyone in the Baltimore/Washington area be willing to give his parents a ride to a reception in their honor on Sunday May 23, 1999? If so, contact Scott on the Internet at <gillis@metro.net>

Received a letter from Ira

Received a letter from Ira Malek, 105-30 Flatlands 2nd Street in Brooklyn, NY 11236. Phone (212) 444-6628. He owed a'38 Century Convertible Coupe while in college in 1948. He writes: "Please put me in touch

with owners of 193 7-1938 Buick Century automobiles. who might be interested in doing some quarter mile runs someplace in the northeast or at the National Meet in Columbus this July.

Truth is ... even the guys in the GS clubs don't know what these cars are capable of. To describe the reality of a '38 Century going through a third of a mile at 65 mph and lifting on it's coils and pulling sounds like a fantasy. 320 cubes with 6.3 compression and a 3.9 rear end has some sparkle."







### over Cars

Two 1938 Centurys, Harry Logan's Sport Coupe Model 66S and Cecil Don's Slant Back Sedan Model 67. The photo was taken on the way to the Western '37/38 Meet in 1997. The covered bridge over Grave Creek is the last one in Josephine County, Oregon. In 1846, the first emmigrant wagon train from Fort Hall, Idaho to travel the southern route to the Willamette Valley camped here. Martha Crowley, age 16, died of Typhoid fever during this encampment and was buried near the creek. This is how Grave Creek got it's name.

### My Daughter's Wedding


By Sam Mahle (#1187)-Clarion, PA

The March/April 1998 Torque Tube had an article on the restoration of the 1937 Century Sport Coupe Model 66S that I drove while in college almost 40 years ago.

My brother Lawrence (Gib) Mahle (#1196)

of the credit as he did the leading and repairs to the fenders and doors. We were surprised to find that someone had done a botched repair around the deck lid that had to be cut out and fixed correctly. Gib says he has about 90 pounds (41 kg) of lead in the repairs.

The last paragraph in the Torque Tube article about my car went like this: "I can't wait until this car is drivable again so I can take it for a cruise just like I did when I was in college. I hope to have this car finished by mid-July, 1998 because my daughter is getting married. What a



thrill it would be to drive her in a '37 Century."

Guess what? That's exactly what I did! I drove the newly married couple, Mr and Douglas Reott, from the church, at the head of the wedding parade. We

our horns and waving to the many bystanders and they in turn waving back to us. And did that Buick get a lot of admiring looks both there and at the reception hall.

Several people came up to me at the hall and went on and on about that car. My daughter and her husband were very understanding about this and the history of it. This is the same car that I took her great-grandfather to Washington D.C. in. This was in1960 when he was 77 years old. I am sure glad that more family history can now be associated with this car.



### 1937-1938 BUICK EASTERN CLUB MEET AND TOUR

SOUTHERN INDIANA MAY19-20-21-22, 1999

By Steve King (#776)

Set in the rolling Cumberland foothills of Southern Indiana, French Lick Springs Resort is more than a resort- it's a tradition built on a colorful past. From explorers to the nation's rich, famous, and politically influential (presidents and gangsters) who came to renew themselves at the bubbling mineral springs. Today the "resort" offers 485 spacious rooms, incomparable recreation activities, 5 restaurants, and 3 lounges. We plan to tour the hills and hollers 3 days with possible stops in Jeffersonville, a local winery, Lincoln's boyhood home, Louisville, and the West Baden Hotel under restoration. Steve and Pat King plan to arrive Wednesday afternoon. Make your reservations by April 15 so maps and information can be sent to you.



### 1999 EASTERN MEET REGISTRATION

NAME		SPOUSE	SPOUSE		
ADDRESS					
PHONE		TOUR CAR-YEAR & MC	ODEL		
Mee	t registi	ration fee-\$10.00/car (hospitality room	, etc.)		
☐ Thursday	5/20	Tour:	#Attending		
☐ Friday	5/21	Tour & Picnic: (\$5.00/person added to meet	(fee ) #Attending		
☐ Saturday	5/22	Tour:	#Attending		
☐ Saturday	5/22	Dinner: FrenchLickSpnngs Resort Cost of Dinner will depend on your choice from t	#Attending he Menu		

Make checks payable to: Steve King (#776)

629 W. Main St., Greenwood, IN 46142-Phone (317) 881-8303

### HOST HOTEL

French Lick Springs Resort, 8670 W. S.R. 56, French Lick, IN 47432 Phone 800-457-4042

Make reservations direct with hotel and

MENTION '37-'38 Buick Club

to get special rate: \$79.00+tax. — 20 rooms are being held until April 15.

# PUMPED UP OVER CALIFORNIA GAS COLLECTION

Harry Logan (#651) - Los Altos, California

While on a Northern California car tour, we visited Atland Erickson ... Auburn, CA. He built an replica of an old gas station behind his house to hold his gas pump and sign collection. That's my '38 Century Coupe in the garage. The next photo shows another view of the old gas station. The photos on the next page show some of his large gas pump and sign collection.







Atland (Al) Erickson in Auburn, CA has collected many antiques in his life but his collection of automobilia is larger than these photos show. Just to the right of the top photo, on page 8, is another building filled with antique and collectible vehicles and more automobile paraphernalia that would make most museums jealous from the sheer vastness as well as quality of his collection.




### SO YOU WANT A PROJECT?

By Harry Logan(#651) - Los Altos, CA

**Dick Oellers** (#1075) in Maine is restoring both a '37 2-door trunk back sedan Model 48 and a '38 4-door trunk back sedan Model 41. Not everyone has the heart to tackle a project involving one car but to take on two cars has to bring forth a standing ovation from the membership. Three cheers.







## A Maltby Bodied Buick

By Victor Lane (#1014)-Wales, U.K.

This photo shows my 1937 McLaughlin-Buick Model 40X. It wears a saloontourer (convertible sedan) body by Maltby's of Folkestone, England. The chassis is a very early 1937 model, received by the British representatives.

Lendrum & Hartmann of London in September of 1936. They dispatched it by road, with a soap box to sit on and a makeshift windshield) to Maltby's for bodying. The car was first registered by it's original owner in London near the end of January, 1937.

One of the most interesting features of the car is its fully powered hydraulic top mechanism. Some of our readers may know better, but as far as I've been able to ascertain, the Maltby arrangement was the earliest fully powered convertible top device on the market. That it was available


on a 4-door convertible is particularly noteworthy. It is driven by hydraulic rams, one on each side, that both raise and lower the top at the touch of a button. The button powers the hydraulic pump.

What's more, the top is so cleverly



designed that it's only necessary to release the over-center clips at the top of the windshield to start low-ering it. There are no snaps or zippers to undo first, and the top is commendably draft (draught) free when raised. An interesting feature is that it's pos-

sible to lay back only the rear quarter of the top, for a landaulet effect. Maltby's specialized in this "saloon-tourer" body, and fitted it in the mid to late 1930's to all sorts of chassis, from Ford to Rolls Royce, but particularly favored Buicks. Most of the chassis were from the McLaughlin plant in Oshawa, Canada. Buicks were very popular in Britain in the 1930's, both because they offered terrific value for the money and because they were greatly favored by the Royal Family. Nine Buicks were sold to Royal Family members between 1928 and 1939.



My car, which I've had for 5, years is entirely Buick from the center of the cowl forward, except for the big Marchal headlamps, which were an optional extra offered by Lendrum & Hartmann. Some cars, including mine, came with

both the Marchals and the standard Buick bullet head lamps. So you could change around as the mood struck, or even presumably mix & match! Also included with the chassis were all four fenders with


both parking and tail lights and sidemount hardware as well as both bumpers. Because Maltby

wanted to use a flat windshield. the cowl was sliced vertically just behind the cowl vent. And a new back half suitable for the flat windshield was welded on. In the

right light you can just see the joint.

My car was in derelict condition when I bought it, although the former owner had had a number of restoration jobs done, such as chroming, re-glazing and the collection of a great many useful mechanical parts. Curiously, he had also gotten together the necessary parts to convert the car to left-hand drive! Not back to lefthand drive. The car was originally built with the steering wheel on the right side, for export to the U.K. When I asked him why he would have wanted to do that here, where right-hand drive is the norm, he said it just seemed to him that

Buicks ought to be left-hookers! So I have a complete steering column with various linkages, a complete pedal set and numerous odds and





them gratis...but you'll have to pick them up here in Wales! It took my restorer and me about a year to re-

ends for a LHD '37

40 series, and any-

one who needs the

bits is welcome to


store the car. It had obviously been well and hard used in its life, and total rebuilds of the engine, transmission, back

> axle (which we gave a 3.9 ratio for easy cruising) and suspension were unavoidable. I often had reason to be grateful to the TORQUE TUBE for the names and addresses of parts

suppliers! There is still a little more noise in the power train somewhere than I'd like, but apart from that the car now runs and goes like new (or better). Being a Buick it is utterly reliable and so ideal for use in weddings, for which it is in regular demand.

People in this country often remark on the flamboyance of the Maltby body and its yellow color, assuming it is so American! But of course the body (which was originally yellow) is the wholly British part of the car! Really, no one who has seen some of the outrageously in-your-face bodies fitted to some Jaguars, Bentley, and many

> other British makes, should ever assume that all British coachwork is formal and stodgy. It never has been!



### The Duchess

By Paul Cook-Wakefield, MA.

The first time I can remember seeing my father's 1937 Buick 2 Door Century Opera coupe was in my grandmother's garage in Lynn, Mass. It was 1958 and I was 6 years. old. I proceeded to jump

into the front seat, try to steer the big wheel and shift through the gears. I was amazed at the type of car it was, the size; and what were those things that you could stand on while hanging onto the door, (running boards??). I had never seen those before!

Before I left the front seat of my first encounter with the Buick, I proceeded to put my finger through the headliner right above the mirror. I didn't realize how fragile the fabric was and thought my father was

going to kill me. Well, I don't think he saw it and that hole is still there today.

I never saw my father drive the Buick. I do not know exactly what year he took it off the road and stored it in his parents garage. When he and my mother bought a new house with a 2 car garage, my father had the Buick towed to the new location. I can remember that when the car arrived at the new house my father started it up. It was running but the master cylinder had leaked and we had no brakes, so we had the car pushed into place and there she remained for the next 33 years.

As I grew up I had a love of cars and mechanics in general. I was always taking apart and putting together something. I was still too young to really start working on the Buick and my farther was too busy with work and other things to really start the Buick back on the road to recovery. So between 1960 and 1969 we just heard stories about the Buick. Here are just a few:

My father called the Buick *The Duchess*. No one knows where the name came from or why, it was just The Duchess, the honeymoon

car. My father and his two sisters used the car to go on their respective honeymoons during the 1940's. The first weading trip the car took was to Philadelphia. My Uncle Larry was telling me the story of how he and my aunt were going over a bridge and one of the wheel bearings froze up. The car went in and out of the shop and they were back to enjoying their honeymoon in Philadelphia, one month before Pearl Harbor.

The Buick proceeded to take the other

members of my father's family on their honeymoons without incident. Many years later in 1992, the year after my father died, the Buick took my sister to her wedding. It was one of the best days of my life.

The Buick also made numerous trips to New York City because my father was very much into opera and attended many performances at the Metropolitan Opera House. He was a lover of music; any and all kinds of music, but opera was his favorite. My brother Jim, who had a big part in restoring the Buick, took great pride and joy in restoring and having rebuilt the radio. Dad always had the radio on when he was cruising. It seemed the Buick was the only car in my fathers family at the time and it was used by everyone.

As I got older I took a greater interest in auto mechanics and started to work on the Buick. I rebuilt or had rebuilt just about everything needing rebuilding, the master cylinder, the carburetor, the radiator, the fuel pump, the generator, the gas tank, and the wheel cylinders. Not to forget the wiring harness and new steering wheel. Though I spent a lot of time tinkering and getting a lot of things accomplished, my interest would fade and the Buick still did not move, but

we moved. My family moved overseas for three years, we came back and I went to college. After college I got my first real job and got married and the Buick sat idle for a good 18 years.

Then I decided to start tinkering with it again in 1988, three years before my father died. But tinkering was all I did, nothing real serious because I thought it was going to take a small miracle to start this car. And then my father died in 1991, taking with him a big part of my heart and all the remaining untold little secrets of the Buick.

A bigger heart lost that day was my sister's. She was even closer to my father than I was so when she got engaged the following year her only request of me, and her dream, was to be driven to the wedding in Dad's car. It was a request I had to make happen no matter what. I had to start and drive a car that had not seen the light

of day for 33 years, and I had I year to make it happen. To my amazement, and with the help of an experienced antique car owner, the Buick fired up within 15 minutes of the first cranking in 33 years. I was in total amazement. What piece of machinery sits idle for 33 years, and with a

minimum of help gets going again. Only those great cars of way back when. We got it all on video tape and its now part of my sisters wedding video.

Now the Buick had a severe overheating problem of which I did not know much. I did not figure it out until some 3 years later, but the one and only time it did not overheat was the whole weekend of the wedding. I how Dad was watching down on us that day.

So now with the heating problem resolved (much debris behind the freeze plugs) I

try to drive the car as much as I can on the weekends during the summer. All this time has passed and I did not realize, until when it finally hit the road, how great a car that 1937 Buick Century is. People love this car.

It will always be in the family. It's one of the symbols my father was able to leave of himself. He loved this car and we loved him.



# 1938 BUICK RESTORED TO ITS Original Security By Walter Morrison (#833)-Oakville, Ontario, Canada

This black1938 McLaughlin-Buick Roadmaster Formal Sedan is special. It's the only survivor of a limited number of rare Canadian-built McLaughlin-Buick Roadmaster Formal Sedans, 227 in total. This one is number 122.


It was built in Oshawa, the home of Colonel Sam McLaughlin. In 1975, my son John and I began restoring this beauty in our garage at home. John who was 15 at the time did most of the body work and painted the car with 12 coats of black lacquer. One of the doors is from a 1939 model, which John restored to fit. A front fender came from a scrapyard in Quebec to replace one that had rusted.

John checked around the junk yard to find a 1963 Chevrolet gas tank that fit. The original gas tank had rusted away and we were unable to find an original replacement.

When the car was scrapped in 1959, a date determined by a 1959 Kodak film box under the front seat, the car had been driven 149,000 miles. It had been sideswiped, reulting in it's abandoment. In 1938, the Roadmaster sold for about \$2,100 Canadian dollars. It was originally sold by Montreal Buick.

I have restored five other cars, a 1934 Buick, 1937 Nash Ambassador, 1937 Imperial Buick limousine which was used in the 1939 Royal Tour, and a 1937 four-door Buick convertible sedan. All of these cars have been sold but I'll never sell my Roadmaster.

The car was used in John's wedding last August and when I'm finished with it, the car will be given to him.



### BUICK Technical CARBURETORS



By Al Weatherly-Mt. Clemens, Michigan

YEAR	MODEL - SERIES	# OF CYL.	CARB #	JET#OF Manufactur	Part#	
1935	40	8	EDIS	Marvel		
1935	50	8	EE1	Marvel		
1935	60	8	ED2S	Marvel		
1935	90	8	ED3	Marvel		
IN 1936 & 1937	NO MARVELS WERE	USED				
1938	40	8		Marvel		
1938	60,80,90	8	CD2	Marvel		-
1935	40	8	Stromberg	EE1	A17671(4)	A17681(5)
1936	40	8	Stromberg		A18181	A18191
1936	60,80,90	8	Stromberg		A18302	A18312
1937	40	8	Stromberg		A18361	A18541
1937	60,80,90	8	Stromberg		A18362	A18452
1938	40	8	Stromberg		A19861	A18452
1938	60,80,90	8	Stromberg	AAV2	A18682	A18692
1939	40	8	Carter	4195	WDO	
1939	60, 80, 90	8	Stromberg	AAV26	A18972	Late 440S wd
1940	40 &50	8	Stromberg	AAV16	A19181	manage (1, 95e) (9/a)
1940	60, 70, 80, 90	8	Stromberg	AAV26	A19182	
1940	60, 70, 80, 90	8	Carter	448S	WDO	
1940	60, 70, 80, 90	8	Stromberg	AAV36	HDAC	19192
1941-42	50 Rear	8	Stromberg		15/16	380043
1941-42	50 Front	8	Stromberg	AAV16	380042	
1941	50 Front	8	Carter	509 or	528	
1941 42	50 Rear	8	Carter	510 or	529 or 543	
1941-42 Single	40,50 Single	8	Stromberg			
1941-42 Single	40,50 Single	8	Carter	487.551	608,663	
	60, 70, 90 Single	6	Carter	549, 664		
1941-42 1941-42	60, 70, 90 Front	8	Carter	528, 535	535	
1941-42	60, 70, 90 Rear	8	Carter	529, 534	. 543, 544	
	60, 70, 90 Front	8	Stromberg		380032	
1941-42	60, 70, 90 Rear	8	Stromberk		1 1/16	
1941-42	40&50	8	Stromberg		&AAV167	
1946-47	40&50	8	Carter	608,663		
1946-47	70	8	Stromberg	AAV26		
1946-47	1.0	8	Carter	609,664		
1946-47	70	8	Stromberg		AAV267	
1942-47	60,70,90	8	Carter	609,664		
1942-47	60,70,90	8	Stromberg			
1948-49	40,50			663 608		
1948-49	40,50	8	Carter	4431262		
1948-49	70	8	Stromberg			
1948-49	70	8	Carter	664 609	. 9	
1950-51	40-50	8	Stromberg	AAU VBC	883 with 62	d bass
1950-51	40-50	8	Carter	725,882	883 With 04	4 Dasc
1950-51	70	9	Stromberg	AAVB26	002	
1950-51	70	8	Carter	The state of the state of the	883 with 625	Dase
1952-53	40	8	Stromberg			A
1952-53	40	8	Carter	882 or	883 with 624	Dace
1952	70 4 bore	8	Stromberg	4AUV26	7	
1952	70 4 bore	8	Carter	8945-SA		
1952	40 & 50 2bbl.	8	Stromberg	AAUVB	67	
1952	40&50 2bbl.	8	Carter	8965		
1953	40 2bbl.	8	Stromberg		67	
1953	40 2bbl,	8	Carter	8825		

Fornished by Al Weatherly BCA #7786 Buck Unlimited



### FRONT AND REAR STABILIZERS

By Harry Logan (#651)-Los Altos, CA

To eliminate side sway and body roll when go-

that dimension "A" (diagram C) is 111/11" (4.29 cm)

on all series cars.

cars still have the

original stabilizer

rubber bushings.

now hard as a rock.

You can replace just

the rubber bushings

or the entire

Check with Be

Many of our

ing around curves. your Buick is equipped with ride stabilizers. As the car tends to sway to one side, it sets up a twist in the stabilizer bars, which the strength of these spring steel bars resists.

1937 DUAL STABILIZERS CROSS STEERING 80-90 SAME AS LAST YEAR) BALANCED

On both '37 and


'38's, the front stabilizer is connected across the front end of the frame as shown in this 1937 diagram above (A).

The stabilizer is mounted on the frame in two rubber bushings which are held in stamped brackets (You can order replacement rubber bushings from Bob's Automoblia or Lynne Steele). The stabilizer bars are joined to the spring seats (lower A arms) through rubber cushioned links (B).

The front stabilizer link consists of a bolt (rod) which passes through the end of the stablizer arm and fas-

tened to it with rubber bushings (grommets) and steel washers held in place by a nut on one end of the bolt. This diagram (C) from the Shop Manual shows a nut at each end of the bolt, but the two original stabilizers I observed only have a nut at the bottom end (The top end is a bolt head).

The lower end of the bolt passes through the spring seat on the lower control arms. When these links are installed, the nut on the bottom end of the link should be tightened so



Automoblia or Lynne Steele. Shown are an original (D) and new Lynn Steele link. They are identical except for the length of the spacer.

The original spacer is 3 1/16" while the Steele one is 2 1/4" (E). The shorter Lynn Steele spacer did not work on my car

Before I reached dimension "A" (141/16"), the nut reached the end of it's threads So I used the longer original spacer and everything worked fine.


Some of our cars are miss-

ing the front suspension "A" arm rubber bumpers (F). You can also purchase replacement bumpers.


> The rear stabilizer on the '38 was called a radius rod by Buick (G).

> Lynn Steele sells replacement rubber bushings for the '38 rear stabilizer (radius rod). You will need four (H). Part no. 50-0302-35.

> Members have reported that you can replace the original 1938 rear shock absorbers with Monroe Magnum 60 #6828 with a little trimming of the rubber bushings.
















ED: Thanks to Bob James (#371) in Canada for sharing this information.

# Technical 1938 BUICK

From the American Electrical Assn.

### BUICK Series 40 1938 8 Cyl.

### **Electrical Equipment** DELCO-REMY

Generator1	101052
Armature1	866789
Field Coil Set	869430
Coll—Right 1	866408
-Laft	866409
Brush Set1	867963
Brush, Main1	880344
Brush Set	860766
Arm Break 1	850759
Spring Brush Main 1	850780
Arm, Bresh	850767
Bearing D. F.	3203
C. E	812823
Cranking Motor	734Z
Armature	823881
Field Coil-Right	812699
-Left	812700
Brush Set	857960
Brunhea (4)	811553
Arm, Brush	810226
Spring, Brush	813521
Bearing, D. E	839345
Clutch	874156
Ignition Distributor	110801
Contact Set	
Arm1	
Point	
Cap	837974
Condenser	
Rotor	
Gear	283994
Weight, Advance1	837944
Spring, Weight	
Dist. Vacuum Control	681 H
Ignition Coll	*526B
Dash Lamp Switch	1404
Dimmer Switch1	997002
Light Switch	994001
Vacuum Switch	4768
Solenold Switch	1542
Generator Control Unit	
Automat, Carb. Control	
Horn-Right	
-Left	999579
Horn Relay	116775
	110113
WD and any might Distance of Co.	A W

#### Lamp Equipment GUIDE

Headlamp-Multibeam	
Prime, Left	667N
Right	667P
Reflector, Multibeam	
Lens, Multibeam	200,100
Left	920491
Right	920492
Gasket, Lens Seal	6084
Molding, Left	920591
Right.	920592
Spring, Lens Retaining	918107
Wiring Assembly	
Fender Lamp	950199
Prime, Front	340A
Lens	
Gasket, Rubber	920196
Rear Lamp, Center	*390A
near Lamp, Center	**390B
Glass, Outlook	922042
Gasket, Outlook Glass	
Rear Lamp—Fender	362,040
Prime, Left	389A
Right	3898
Door, Left	922187
Right	922188
Lens	to the same of the same
Gasket	
Spring, Lens Retaining	921860
Spring, Door Catch	921863
Screw, Door Retaining.	922446
	BEE-240
*On Models 41, 48.	
**On Models 40C, 44, 46, 460	400, 47.

#### Locks and Keys BRIGGS & STRATTON

Ignitio	on Lock	Ĭ.	 	+++-	45922
	Series				
	Blank				

#### Carburetor Equipment STROMBERG

For Standard Air Cleaner
Carburetor AAV-1A-18681
Float Needle Valve & mann
Seat
Metering Jet (.048")P-19442 By-Pass Jet (Pump)
No. 63

#### Part No.

By Pass Jet (Econ) No. 62 Check Valve. Idle Tube. Pump. Gasket Set. RK-Kit.	P-18144 P-23325 P-23322 J-5317G
For Heavy Duty	Air Cleaner
Float Needle Valve	A-18691
Seat Metering Jet (.046*)	P-22499
No. 63 By-Pass Jet (Econ)	P-23742
No. 66. Check Valve	P-23606 P-18144
Idle Tube	P-23325 P-23322
RK-Kit	

#### Shock Absorbers DELCO


Shock Absorbers Complete	te
Front-Right	1947A
—Left	1947B
Rear R. & L.	
Original Equip	11008
Service Repl ment.	11058
Gasket, End Cap (front)	44933
Gasket, Filler Plug (frnt.)	
Rod Guide & Seal Assay	F
Gasket, Rod Guide Cork	316773
Gasket, Rod Guide Cork	
(rear)	316753
Gasket, Rod Guide Rubbe	
(rear)	316700
Bushing, Eye Rubber	a washing
(rear)	302790

### Stabilizer Parts:

Link Rod-Front	5309790
Bushing Kit	743
Rubber, Link	5302384
Retainer, Rubber	43468

#### Windshield Wiper Equipment TRICO

C	losed and Convertible Motor - Central Mount	
	ing.,,,,,,,,,,,,,,	SK-24-1
	Wiper Arm, Both Sides	Ger Pari
	7"	
	Ares, Nut	75072-C
	Blade, 814"	P-778-30-0
	Chain Housing & Link	
	age, L. H. Side	
	Chain Housing & Link-	
	age, R. H. Side	
	Rubber Gasket	
	Control Knob & Stem	
	Felt Washer for Motor	
	Lever	
	Spring & Link Clip for	
	Motor Lever	76125-J
	Motor Renewal Parts	
	Set	Sp 1075
	Shaft with Lever	76235-J
	Motor Kicker	8897-17
	Linkage Repair Set	
	and the second second	



### BUICK Series 60, 80, 90 1938 8 Cyl.

#### **Electrical Equipment** DELCO-REMY

Generator (60)1101053
(80, 90)1101055
Armature
Field Coil Set
Coil-Right1866408
-Left
Brush Set
Brush, Main
Third1850768
Arm, Brush
Spring, Brush-Main1850760
—Third1850767
Bearing, D. E 3203
C. E 812823

Granking Motor 727W
Armature
Field Coil-Upper 826281
-Lower 826282
Brush Set
Brushes (4) 811553
Arm, Brosh 810226
Spring, Brush 813521
Bearing, D. E 810620
Clutch
Ignition Distributor 1110801
Contact Set
Arm
Point
Cap
Condenser
Rotor1836893
Gear
W-1-by A.F. 1997044
Weight, Advance1837944 Spring, Weight 825515
Dist. Vacuum Control., 58111
Indiate Coll Sontrol, Sold
Ignition Coil *5268 Dash Lamp Switch 1404
Dimmer Switch1997002
Light Switch1994501
Vacuum Switch 1868512 Stop Light Switch 476S
Solenoid Switch 1542
Generator Control Unit 1118213
Automatic Carb.
Control1990102
Horn-Right
-Left1999520
Horn Relay

\*Replace with Universal Generator No. 52-U.

\*Also order 1871821 Bracket.

#### Lamp Equipment GUIDE

Same as Buick Series 40 1938 8-Cyl.

#### Locks and Keys BRIGGS & STRATTON

Ignition Lock	45925
	8000-9499

### Carburetor Equipment

ROMBE	RG
dard Alr	Cleaner
	A-19682
	P-22499
(.052*) Pump)	P-19442
	.P-23742
	P-23348
	.P-18144
	ir Cleaner
	A-18692
	P-22400
(.050*)	P-19442
D	
	.P-23742
Econ)	
	ROMBE  ndard Air  V-2  Valve &  (052*)  Pump)  Econ)  Fy Duty A  V-2  Valve &  (050*)  Fump)  Econ)

#### Shock Absorbers DELCO (Series 60) Same as Buick 40 1938 8-Cyl.

Part No.

(Series 80 and	90)
Shock Absorbers Comple	
Front-Right	19020
Rear—R. & L.	19020
Original Equip.	11005
Service Repliment.	11058
Gasket, End Cap (front)	
Gasket, Static Load Val-	
Nut (front)	828629
Gasket, Inertia Weight	
Cover (front)	057096
Gasket, Filler Plug (fr.)	827799
Rod Guide & Seal Assy.	
(rear)	5316773
Gasket, Rod Guide Cork	
(rear)	
Gasket, Rod Guide Rubbe	er
(rear)	
Bushing, Eye Rubber	
(rear)	302790

#### Stabilizer Parts:

Link Ro	d-Front	5305633
Rubber,	Link	1057228
	r, Rubber	

#### Windshield Wiper Equipment TRICO

(Model 60 Only)

(Model of Convertible Same as Buick 40 1938 8-Cyl. EXCEPT: Motor—Central Mount. 5K-23-1 ing.....SK-2: Closed (Models 80 & 90 Only)

losed (Models 80 & 90 Uniy)

Motor Central Mounting ... SS-8

Wiper Arm, Both Sides, ... 76570-46-C

Arm Nut ... 750/2-C

Blade, 9' P-778-33-C

Chain Housing & Linkage, L. H. Side. ... 77576-C

Chain Housing & Linkage, R. H. Side. ... 77577-C

Rubber Gasket ... 77577-C

Rubber Gasket ... 77573

Control Knob & Stem. ... 75830-15-C

Felt Washer for Motor

Lever ... 75896

Spring & Link Clip for Motor Lever ... 76125-J

Motor Renewal Parts

Set ... Sp 1082

Shaft with Lever ... 76195-2-J

Motor Kicker ... 8897-17

Linkage Repair Set ... Sp 1083 Motor-Central Mount-

### RE-CHROMING WINDSHIELD WIPER TRANSMISSIONS PART

By Don Micheletti (#250) Menlo Park, CA

A tech tip on how to remove the windshield wiper transmission shaft and gear before rechroming appeared on page 18 of the Nov/Dec '98 issue. It was re-printed from an earlier Torque Tube. To do this, it suggested drilling a small hole in the back of the transmission and then using a punch to drive the shaft out.

Here's a better way! It does not require drilling a hole in the back of the transmission. Instead simply stack a few washers over the shaft and screw on a 10-32 nut. Then tighten the nut against washers and pull the shaft out. It worked for me.




photo of wiper transmission with washers and nut




### Technical WINDSHIELD WASHERS

Richard Oellers, (#1075)-Winthrop, ME

ED: Buick released a 6 page document entitled "1938 Buick Accessories" dated November 1, 1937. It lists all 1938 accessories plus ones used on 1937 and previous models that you could still order in 1938.

Listed as a new accessory for 1938 was a windshield washer part number 985292. Group number 8.792. So it appears that from at least November 1, 1937, you could order an accessory windshield washer on a 1938 Buick. The list price was \$4.75. I have never seen a car with an original washer, but Dick Oellers in Maine owns a 38-41 with one.






Here's his story:

My '38 wiper transmissions were factory drilled and piped. On the exterior were threaded holes with small screws, You removed the screws and installed the nozzels, then rotated them for correct direction. Voila!

The washer was mounted on the left hand side of the fire-wall, in the space between the voltage regulator and the outside edge of the firewall. The resevoir and pump assembly was connected to both the windshield wiper vacuum line and a "button" control mounted under the dash above the parking brake handle.




ED: The washer was vacuum operated like the wipers. It was not battery operated.


### HOOD RUBBER Technical BUMPERS




By Harry Logan (#651)-Los Altos, CA



Most 1938 Buicks have two 1/4 inch holes at the front of the hood (just above the top of the grille) to hold rubber bumpers. These protect the hood from rubbing against metal.





Some early 1938's do not have these holes. The car in this photo without the holes was assembled in December, 1937. So there must have been a production change, probably in early 1938. You may want to add these holes and rubber bumpers if your '38 does not have them.





### Technical REAR WINDOW SUNSHADE

By Dick Oellers (#1075)-Winthrop, ME

'37 and '38 sedans came with a roller type sunshade located behind the rear seat. It was mounted to the flat luggage shelf just below the rear window. This item is often missing today as many owner removed them when the cloth deteriorated.

The shade was pulled up from its roller mounting and was secured by slipping a tab over a rounded metal peg just above the rear window. This peg looks much like a grease fitting. These shades were also used on other GM sedans of that era.





### WELCOME

Members

Ric Anderson (#1402) 516 Harvey Dr. Racine, WI 53405

Ron Johnson (#1403) 18 Connaucht Lemont, IL 60439 38-47

E. H. Trezevant Jr. (#1404) 5716 Koon Rd. Columbia, SC 29203 37-bearse

Greg Korzeniowski (#1405) 361 Napoleon St. Carleton Place, Ontario Canada K7C 3Y3 37-41 McL John Wilson (#1406) P.O. Box 291 Pinch, WV25156 38-47 & 38-46

Clay Stephens (#1407) P.O. Box 205 Westport, NY 12993 37-46C

Charlie Marion (#1408) 727 Beavers Rd. Canton, GA 30115 38-66C

Ariel Baysre (#1409) Villa Maria 9 de Julio 27 Cordoba, Argentina C.P. 5900 37-91F Pentti Tiira (#1410) Kirvesmiebentie 12 Kellokoski Finland 04500 38-80C w/Nordberg body

Joseph Talbot (#1411) 301 S. Blackstone La Grange, IL 60525 38-46

Jerry Pasquariello (#1412) 680 Rifle Camp Rd. West Paterson, NJ 07424

KarlHeinz Pydde (#1413) 267 Mount Morton Road Belgrave Heights, Victoria Australia 3160 37-48 Tbeodore Porczynski (#1414) 250 Aquetong Road New Hope, PA 18938 38-46

Howard Kriebel (#1415) 90 6th Avenue Collegeville, PA 19426 38-61 38-68

Brian Arrner (#1416) Merlewood Lancaster Road Pilling Preston, Lancashire England PR3 6AE 38-41 McL

Greg Field (#1500) 3577 Grandview Blvd Los Angeles, CA 90066 38-66C 38-80C

### Parts FOR SALE

1937 PARTS FOR SALE	
Limited Sidemount fenders54	100
plus shipping	
David Bylsma (#117)	
7802 Chevalier Ct.	
Severn, MD 21144	
(410) 551-7236	

PARTING 1937 & 1938 The following is just a portion of the parts available. Call with your needs.

1937 PARTS	
40/60 Series rear brake cables, good condition	\$40 pair
Coupe taillight, no stanchon or T bar	
80/90 series trunk hinges	\$125
Master and deluxe heaters	
Roadmaster rims	
Roadmaster axics	\$100 pair
Roadmaster front suspension	call with needs
Coupe & 2 Dr. Sedan side stainless, complete sets	\$75
Century brake & clutch pedal assembly	\$35
Century radiator	\$75
Special radiator	\$75
Rear springs 40 & 60, good condition	\$100 pair
Radio delete plates	\$15
Small series throttle linkage	\$25
Big Series rocker assemblies	\$50
Fender lights	\$65 pair
Trunk lights, complete	\$50
Tail lights with lenses, all series	\$50 pair
Wiper transmissions	\$50 pair
Special manifold	\$75
Throttle cable	\$20
Special transmission	
Special splash pans	
Century hood	
Headlight switch	\$20
Radio grilles	\$15
Wiper motors	\$15
Trunk hold-up arms	\$20
Sun visors	
Bumpers	\$30 each
Bumper arms	\$15 each
Steering wheel	
40 & 60 running board brackets	
Buick creast badge for hood trim strip.	

(Parts For Sale continued from page 25)	
Gas pedal	\$15
Small and large series generators	
• 1938 PARTS	
Radio, working	\$300
DeLuxe Heaters	\$75 each
40/60 series front bumper, not perfect	\$100
40 & 60 sedan trunk lid, no rust	
Breather tubes	
Trunk hold-up arms	\$20
734Z starter with solenoid	
Horn button	
Special hood lettering	
Defroster ducts	
Wiper transmissions	
Rear license plate stand, bracket & light for sedan	The state of the s
Tail lights, complete	
Assist straps with screws	
Throttle cable	
Special radiator	
Battery tray	
Generator	
Special manifold, complete	
Special hood sides & tops	
는 사람이 되었다. [170] 보기 보기 보기 되었다. [170] 보기 보기 보기 보기 보기 되었다. [170] 보기	
Grille, no cracks, minor pitting	
Century radiator	
Special coupe window moldings	
Cigarette lighter	
Century motor, rebuilt, complete with AAV-2 and new clutch	
Rear muffler hanger, NOS	
Grille, some pitting	\$100 pair
• 1937-1938 PARTS	
Special Sidemount covers	
Opera seat stands, 40/60 series	
Special running boards, solid cores	
Headlight buckets	
40-60 kingpin sets	
Starter drives	
Large series fan belts, new.	
Map light switches	\$15
Small series spark plug covers	\$40
Rear fender splash aprons	
Big Series manifold ends	\$50
16" beauty rings	
2 Door rear ash trays	
Headlight bezels	
Trunk hinges	
Front arm rests	\$25 pair
40 & 60 rear vent windows, need plating	

(Parts For Sale continued from page 26)	
Rear view mirrors	\$15
Special rear motor mounts	
Century rear motor mounts	
40 & 60 4 dr. sedan doors	
Front vent window frames & mechanisms	
Big Series fuel pump cores	
Keyed ignition switches	
4-Post voltage regulator, used.	
15" Beauty rings	
Headlight adjusting buckets	
Dave Tacheny (#997)	moroto pan
11949 Oregon Ave. N.	
Champlin, MN 55316	
(612) 427-3460	
(612) 727-3400	
• PARTS	
1936- possibly same as 1937 Century/Roadmaster.	
Two disassembled transmissions, large series \$85 each or \$1	50 for both
Large series intake manifold	
1937-1938 all series voltage regulators, 4 terminal, rebuilt	
1938 Century/Roadmaster AAV-2 with automatic choke	
Steering wheel core with center horn button	
1937 40 Series SpecialTransmission, short tailshaft, open driveling floorshift.	
Same bolt pattern as Buick special	\$125
Valve cover, clean, painted	
Bellhousing	
Thermostat housing, 2 piece	
Exhaust center manifold section, 40 series with heat riser.	
Kingpin set, Thompson 36SN, new	
New pressure plate, 10 " diameter, coarse spline clutch disc\$	
Carburetor, AAV-1. Has been rebuilt, sitting in garage for several years	
1937 40/60 Special/Century 3.9 rear end, complete drum to drum	0.27
with torque tube from '37 Century	
Bumper cores, front or rear. Need rechroming	\$30 each
• 1937 ROADMASTER/CENTURY PARTS	4-4-
Engine, was running. No manifolds or carb	
Transmission	
Carburetor, AAV-2 Stromberg. Need rebuild	\$190
Marvel Model CD 1B carburetor, complete with choke.	1,000
Was NOS but has been sitting for years	
Suspension, front end parts, used	inquire
• 1937 ROADMASTER PARTS	
Rear end, complete. No drums	
Front seat frame. Good worrd. Has adjuster. No cushion springs	
Front suspension parts	inquire
All prices plus shipping	
Dave Powers (#894)	
27732 Paseo Barona, San Juan Capistrano, CA 92675 (949) 493-1199 eve	nings

### 1938 SPECIAL PARTS

Special complete drive train.

Keith Smith

Phone: (530) 622-4606 E-mail: k6smith@chw.edu

### INFORMATION WANTED

Information on putting any 3.9 gears into a '38 Buick Limited.

Thanks.

David Bylsma (#117) 7802 Chevalier Ct., Severn, MD 21144 (410) 551-7236

### 1937 SPECIAL PARTS — Front clip, less grilles, Includes:

- Radiator Instrument cluster Starter Repro instrument cluster glass
- Rebuilt front shock absorber Front & rear bumpers Rebuilt water pump
- License plate light assembly for a fast back sedan 2 water pump rebuild kits
  - Transmission
     2 parking light lenses
     Steering column
     Set of king pins
     2 voltage regulators
     Trunk handle

There are more items that are not listed......\$100 takes it all

Harvey Hedgecock 13730 Adrian St., Poway, CA 92064 (619) 679-7084

### 1938 PARTS FOR SALE

- 2-outside locking door handles in excellent condition.
  - 53/16" long from end of shaft to key entry.
- 2-outside locking door handles. Can be in poor condition so long as they have the shaft keyed.
  - 5" long from end of shaft to key entry.
- 4 nice bumper guards.

  John Baine (#1090)

RR 2, Bedford, Ontario, Canada 13Z 2A5 (905) 775-2622

### 1938 PARTS & LITERATURE FOR SALE

- Colored folder showing all series cars and new features......\$30
- Radio installa tion manual, reprint......\$5
   All prices plus shipping

John Johnson (#697) 276 N. Seymour Ave. Mondelein, IL 60060 (847) 566-5005

### PARTS DELIVERY

Presently entering into correspondence with members who may require heavy chassis and body parts such as axle, differential, transmission, engine block, springs, rims, brake drums, doors, hoods, trunk lid, bumpers etc. Free delivery of parts to Buick National Meet in Columbus,

Fall Carlisle and Hershey. 10% of agreed price required in advance.

Send itemized list of small parts required

(plus 50 cents for postage) and I'll quote you a price and condition. Parts cars also available.

Robert James (#371)

P.O. Box 531, Whitby, Ontario, Canada L1N 5V3

FAX: 1-905-655-5310

### Parts WANTED

### · WANTED: 1937 PARTS

Desperately seeking a trunk lid for my 1937 Special Convertible Coupe Model 46C. Thank you. Clay Stephens (#1407) P.O. Box 205, Westport, NY 12993

1

### Gars FOR SALE

### FOR SALE: 1937 LIMITED

1937 McLaughlin-Buick Limited 7 passenger sedan. Runs and drives well, in good overall condition. New wide whitewall tires.

\$9.500 offer.

Dave Tacheny (#997) 11949 Oregon Ave. N. Champlin, MN 55316 (612) 427-3460



### FOR SALE: 1937 CENTURY

Model 61 4 Door Trunk Back Sedan. Very original. Runs strong. New white wall tires. Nice original interior. Many extra parts, manuals in trunk. Original spare on rim with stripes. Photos available.

### \$8,000

Steve Nathanson (#656) 69 Terrace Rd.. Walnut Creek, CA 94596 (925) 947-6711

### FOR SALE: 1938 SPECIAL

My father has a 1937 Special, Business Coupe Model 46. He restored the car several years ago but lost interest in it ( too many projects....he is finishing a '59 Caddy convertible at present). The car is original and A-1 shape mechanically, but it needs to be repainted and upholstered. I can e-mail photos if anyone is interested in it. The car is in central Arkansas. He is asking **\$4,000** 

Bill Swartzwelder

(father's phone number) (870) 447-2596 (son's e-mail address) Wswartzwel@aol.com

### FOR SALE: 1938 CENTURY

Model 61 • restored and updated with modifications • Engine balanced, inserts, hardened valve seats etc. • 4 barrel carb, full synchro transmission • 3.4 open drive rear end, radial tires • Stock appearance but a great driver!

\$14,995 Call for details.

John Harter (#849) (949) 492-7674-home (949) 492-5413-office



### Back Tssucs Still Available!

THE FOLLOWING BACK ISSUES ARE AVAILABLE FOR \$4.00 EACH POSTPAID.

- 1991-1992 Volume X Numbers 1 through 8
- 1992-1993 Volume XI Numbers 2, 4, 5, 6 and 7
  - 1993-1994 Volume XII Numbers 2, 4, and 6
- 1994-1995 Volume XIII Numbers 2, 4, 5, and 6
- 1995-1996 Volume XIV Numbers 3 through 6
- · 1996-1997 Volume XV Numbers 3 through 6
- 1997-1998 Volume XVI Numbers 1 through 6
   Please make your checks payable to:

The 1937-1938 Buick Club, 1005 Rilma Lane, Los Altos, CA 94022 USA

### Gars WANTED

### **1938 WANTED:**

1938 Century Opera coupe, prefer with sidemounts. Nice solid driver w/good to excellent mechanics. Contact:

Ronn Pittman (#1188) 1024 S. Raddant Rd. Batavia, IL 60510-3349 (630) 879-7393

### **CONVERTIBLE SUN VISORS**



\$165.00 each

These are authentic visors. All parts are chrome plated.

### WALLACE WAMSLEY

(619) 283-3063

4732 Bancroft Street #7, San Diego, California 92116

### 1904-1965 BUICK RESEARCH SERVICE

More information and detail about your specific 1937 or 1938 Buick year, model and serial number than you can get from any other source. SATISFACTION GUARANTEED.

Complete Research Package \$50.00, \$60.00 if shipped outside the USA.

Additional information available upon request, or send year, model, serial number, engine number, car photo (if available) and Fisher Body data plate rubbing.

### 1937 BUICK HIGH QUALITY VIDEO

1937 Buick video made from the only known copy of a 16 mm black & white sound film produced by Buick Motor Division in 1937. The tapes have been made by a professional video dubbing studio. They are very high quality and are produced from a digitally mastered original. Video runs approximately 32 minutes and contains a number of segments showing the construction of the 1937 Buick and Buick's place in American society. Historically significant item. SATISFACTION GUARANTEED. \$39.95 including shipping.



### TERRY DUNHAM

AUTOMOTIVE RESEARCH SERVICES

P.O. Box 4057, Apopka, Florida 32704-4057 • Phone 407-880-0797 • e-mail: BUICKOHV@aol.com.



### FRONT FLOORMAT 1937-38 All Models Black or Brown FF-378.....\$195.



### 1937-38 BUICK



DOOR WEATH	HERSEAL-SPONGE	
	DW-378	
Clip-in	DW-80	\$3.25 ft.
Clips	WC-80	\$ .75 ea.
DOOR BOTTO	M SEAL	
Clip Type	DW-369	\$2.25 ft



AUTOMOBILIA

DOOR BOTTOM SEAL Clip TypeDW-369 \$2.25 ft	
TRUNK SEAL-SEDANS. 1/2* Wide; Ser. 80-90TW-371	
Sedans, 3/4* Wide; Ser. 40-60TW-371S\$37.50	
TRUNK SEAL For COUPES 5/8* x 1*	






Sponge ..... TL-369 ..... \$2.00 ft. 1/2'x1'x16' TL-1129 ...... \$47.50

HOOD REST PADS, 1937-38 6-8 Per Car. 




CLUTCH and BRAKE PEDALS Series 40-60 Brown ...... CB-343BN ...... \$5.95 ea.














1937 ONLY! ACCELERATOR PEDALS Series 40-60 Back. AP-37BK .....\$32.00 





SHIFT BOOT, 1937-38 Series 40 Only! Black ..... \$ 9.25

Series 80-90 Black ONLY.... \$ 8.50

DOOR SILLS: Trim To Fit



OUTSIDE DOOR HANDLE CHROME and RUBBER GROMMETS. 1 FERRULE & 1 GROMMET Per Set. 1937...... DGF-296.................. \$5./Set 1938...... DGF-380...... \$5./Set






2-Door \$62/pr. 4Door \$93/set. GLOVE BOXES; \$27. ea. PARKING LIGHT LENS......\$18.00 ea

1938 TRUNK HANDLE/LIGHT MOUNTING SEAL, .... DH-381 ..... \$8.95



CARB. KITS:CARTER.....CK-360C .\$27.00 STROMBERG...... CK-37XS .\$27.50

MOTOR MOUNT, FRONT, All Models





VISOR "VANITY" MIRROR. VM-379 ..... \$27. ea.

TBK-343 .....\$27.00


TORQUE BALL SEAL KIT. All Models

LICENSE PLATE FRAMES. Chromed Brass LF-333P.....\$62. Pair



TRUNK HINGES for 40-60. Chrome Plated \$150. pr.

FRONT END PARTS For	40-60 Series
Upper Outer Kit	\$39.50
King Pin Sets	
Lower Inner Bushings	\$20.00
Tie Rod End	\$27.00



1937 HUB CAPS. All Ser ..... HC-37 .... \$60. ea. WHEEL Beauty Rings. 15' or 16' ....... \$99./Set of 4 1937 or 38 HOOD ORNAMENT......\$85.



SOME OTHER ITEMS WE STOCK; BEARINGS. DECALS, ENGINE PAINT, DECALS, SHOP MANUALS, PARTS BOOKS, BODY BOOKS and MORE. SHIPPING;10%. max.\$9. min. \$4. Prepaid. C.O.D. Add \$5.

BOB'S AUTOMOBILIA BOX 2119 ATASCADERO CA. 93423 TELEPHONE (805) 434-2963 .VISA- MASTERCARD-DISCOVER or C.O.D. CATALOG #45 \$5.00 - PHONE ORDERS - (Write For Catalog)



### Buick Upholstery and Top Kits

Since 1977

Hampton Coach has been producing the finest quality interior and top products available for GM cars. We offer complete interiors, seat upholstery, tops and related components. Call our Inquiry Department today, toll free at 1-888-388-8726 and we'll be happy to discuss your Buick's needs.

### HAMPTON

Phone 508-388-8047 (Toach)

P.O. Box 6, 6 Chestnut Street, Amesbury MA 01913



Restoration and repairs that are correct and authentic. "I know your Buick." Former Director of Long Island, NY Chapter now has fully equipped shop in North Georgia. Ron Stanger, BCA #21079

Classic Car Works Ltd., 3050 Upper Bethany Rd. Jasper, GA 30143 Phone (770) 735-3945




### onaldson Co.

2533 W. Cypress St. Phoenix, Arizona 85009 (602) 278-4505



Thru 1953 Call or write for brochure



RESTORATION



SERVICES

Running Board / Rocker Moldings

1934 thru 1940

SSAE for Information

**BUICK RESTORATION SERVICES** 

P.O. BOX 442, PERRY,

MICHIGAN

48872



1953

### HARNESSES

AUTHENTIC REPRODUCTION WIRING SYSTEMS THRU 1953 HAND CRAFTED WITH THE FINEST MATERIALS EACH SUPPLIED WITH: LIMITED WARRANTY INSTALLATION INSTRUCTIONS SCHEMATICS

ALSO OFFERING: WIRING SUPPLIES CATALOG OR INFORMATION S5



BOX 435 WAYNE, PA. 19087

